

ShopBot Basic Operation and Control Layout

Revision 1.1

May 19, 2015

1. Buttons and E-Stops




2. Setting up new file

- Open Vcarve and create a new file
- Measure and input width, height, thickness of stock
- Set coordinate system origin
- Select units

3. Creating drawings

- **Option 1:** Import from DXF file
 - File Operation → Import vectors from a file
 - Delete extraneous lines
 - Join open vectors



Tools to close open vectors

- Place in desired position on material, resize, etc. using Transform Objects tools




- **Option 2:** Manually draw in Vcarve
 - Drawing tools:



4. Creating toolpaths

- Toolpaths > Show toolpaths tab
- Material Setup > Set...
 - Double check zeros

- Set rapid Z clearance
- **Select toolpath type and edit parameters**
 - Most common: profile and pocketing



- Input cutting depths
- Select tool and material (double check feeds/speeds)
- Double check pass depths
- Set machine vectors
- Add tabs, leads, and ramps if necessary
 - Use ramps whenever possible - it's better for the machine
- All parts must stay attached during machining. If the depth-of-cut is deeper than your material thickness, you **MUST** use tabs to secure parts to the rest of the stock
- When cutting all the way through material, cut 0.005" - 0.010" beyond material thickness into spoilboard. More than this is unnecessary and will require us to replace the spoilboard more frequently.
- Calculate and check preview of toolpath
- Close preview screen and **save toolpath**
- **Rename the file to something meaningful**

Running the Shopbot


1. Securing the stock

- All stock must be secured using screws
- Keep all fastening features (screws, clamps, bolts, etc) outside the cutting volume for your job!
 - Pre-drill pilot holes in your stock
 - Make sure tool will not hit screw heads. This may require either countersinking screw holes or adjusting the safe travel height
 - Notify a mentor if the fiberboard base plate needs replacement

2. Turn ON the Shopbot


3. Open ShopBot 3 software

Control Panel:



To manually jog spindle:

- Click yellow button on control panel to open manual jog Key Pad:




- Move spindle either by:
 - Clicking on arrows in Key Pad
 - Using arrows on keyboard (page up/down controls z-axis)
 - Typing values (in inches) into the “Go To Location” box and clicking on the green “Go To” button

If at any point the spindle hits the mechanical travel limits on any of the three axes, the zero of that axis will need to be reset! This will be very loud. Your part may be ruined if the zeros are not corrected before running a toolpath.

4. Load tool

- **Power to the spindle MUST BE OFF when performing a tool change.** The spindle power switch is located under the spindle control box. “Green” indicates “ON”, “Red” indicates “OFF”.
- A mirror has been installed so the state of the spindle power can be easily assessed.
- **The software jog window MUST BE CLOSED before performing a tool change.**
- Although spindle power must be OFF, it is **recommended to leave the ShopBot power switch ON during a tool change** (when ON, power is supplied to the stepper motors to prevent you from accidentally moving the gantry and losing your zeros)



- Remove dust collection skirt. You may need to manually raise the spindle to do this.
- Load tool with appropriate collet using wrench and collet wrench. You do not need to fully remove the collet to change the tool; simply loosen the collet cap until the tool can slide out
- If performing a collet change, ensure the collet is fully snapped into the collet cap before screwing the collet cap back on

5. Zero X and Y axes

- Open Key Pad from ShopBot 3 Control window
- Jog spindle to desired zero
- Click Zero Axes button on Keypad
- Check X- and Y-Axis boxes
- Click Zero

6. Zero Z axis

- Open Key Pad from ShopBot 3 Control window
- Jog spindle to rough center of cutting area
- Place Z-zero plate directly under tool
- Attach copper clamp to tool
- Ensure no contact between clamp and plate
- Close Keypad
- Click Z zero button on control window and follow on-screen instructions

6. Load toolpath file

- When you are confident in your setup, click the “Cut Part” button on the Control Panel
- Select and upload the desired toolpath file
- Follow the onscreen instructions. Spindle will start automatically when toolpath begins. However, **spindle speed is not set by computer.** It must be set manually using the knob on the side of the machine. Pay attention to how the machine is performing and adjust accordingly.

Do not leave the machine unattended while running!
You must be close enough to hit stop on the computer or to shut off the machine if necessary.