3D Printing Rules & Safety



For questions and concerns, contact mw-3Dprinter@mit.edu

Safety Equipment

- Safety Glasses
- Gloves (recommended for post-processing)

Hazards

- Extruder and motors are **HOT** during operation
- Extruder and motors may be HOT at any time
- PINCH POINTS while machine is moving
- Removal tools are SHARP

Dos

- Do clean up after yourself
- Do inform a mentor of machine errors or damage
- Do inform a mentor of missing tools or supplies
- Do ask a mentor if you have any questions or concerns
- Do exercise caution when using cleaning tools

Don'ts

- Don't use the printers unless you have been trained
- Don't attempt to modify or fix a printer without mentor approval
- Don't let 3D printing become lazy engineering!